

TEST REPORT

Report No.: HC50159A/2016 Page: 1 of 7 May 31, 2016 Date:

VECOW CO., LTD. 12 F, NO. 111, ZHONGCHENG RD., TUCHENG DIST., NEW TAIPEI CITY, TAIWAN, R.O.C.

The following merchandise was submitted and identified by the vendor as:

Product Description:	High Performance Fanless In-Vehicle System
Style/ Item No.:	IVH-9016-PoER505M/ No.2
Quantity:	Total 1 set
Testing Period:	May 30, 2016

We have tested the submitted sample(s) as requested and the following results were obtained: **Test Required:** (According to client's test specification, please see following sheets in detail.)

- 1. Random Vibration Test
- 2. Mechanical Shock Test

Test Results: - PLEASE SEE ATTACHED SHEETS -

Signed for and on behalf of SGS TAIWAN Ltd.

Winson Tseng Asst. Manager

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction unadviful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 SGS Taiwan Ltd. 台灣檢驗科技股份有限公司

No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sas.com

Member of SGS Group



TEST REPORT

Report No.:	HC50159A/2016			
Page:	2	of	7	

1. Random Vibration Test:

Test Equipment:

Name	Brand	Model	Serial No.
Vibration Test System	King Design	EM-800F2K-50N120	RU104080389
Controller	Dactron	COMET 200	10539718
Control Accelerometer	PCB	353B34	139174
Vibration Tester	UNHOLTZ-DICKIE	SAI60-H560BAC/2/ST	474
Controller	Dactron	LASER	7110357
Control Accelerometer	PCB	353B34	143549

Lab Environmental Conditions:

Ambient temperature:	(25 ± 3) °C
Ambient humidity:	(55 ± 20) % RH

Test Method/ Specification:

Test Method:	<u>IEC 60068-2-6</u>	4, Edition 2.0:20	08 and client's	request	
Sample condition:	Operating (exec	Operating (execute Burn-In Test)			
Wave form:	Random				
Frequency:	<u>(5 ~ 500) Hz</u>				
	Frequency (Hz)	Left Slope (dB/Oct.)	PSD (G ² /Hz)	Right Slope (dB/Oct.)	
	5	-	0.05	0	
	500	0	0.05		
	➡> equivalen	t to 5.0 Grms			
Direction:	X, Y, Z axes (se	ee photo 3 ~ 5)			
Duration:	<u>30 minutes/ axi</u>	S			

- Examine the appearance of specimen(s) by visual check and perform functional check after this test
- Functional check: Turn on the power of specimen then execute test program "Burn-In Test" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

台灣檢驗科技股份有限公司___t (886-2) 2299-3279

f (886-2) 2299-9558



TEST REPORT

Report No.:	HC:	50159A/	2016
Page:	3	of	7

Specimen:

Style/ Item No.: Quantity:

IVH-9016-PoER505M/ No.2 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
IVH-9016-PoER505M/ No.2	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC:	50159A/	2016
Page:	4	of	7

2. Mechanical Shock Test:

Test Equipment:

Name	Brand	Model	Serial No.
Shock Testing System	LANSMONT	65-81 TTSII	M-13418
Data Acquisition and Analysis System	LANSMONT	103570-2-В	0503-73
ICP Accelerometer	PCB	353B14	79712

Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	(55 ± 20) % RH

Test Method/ Specification:

Test Method:	IEC 60068-2-27, Edition 4.0:2008 and client's reque
Specimen Condition:	Operating (execute Burn-In Test)
Pulse shape:	<u>Half-sine</u>
Acceleration:	<u>50 G</u>
Velocity Change:	<u>11 ms</u>
Shock direction:	<u>6 faces ($\pm X$, $\pm Y$, $\pm Z$ axes, see photo 6 ~ 11)</u>
No. of shock:	3 shocks/ face (total 18 shocks)

- Examine the appearance of specimen(s) by visual check and perform functional check after this test
- Functional check: Turn on the power of specimen then execute test program "Burn-In Test" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279

f (886-2) 2299-9558



TEST REPORT

Report No.:	HC:	50159A/2	2016
Page:	5	of	7

Specimen:

Style/ Item No.: Quantity: IVH-9016-PoER505M/ No.2 Total 1 set

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
IVH-9016-PoER505M/ No.2	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC:	50159A/	2016
Page:	6	of	7

Test Photos: 1. Appearance of specimen 2. Appearance of specimen 4. 3. Random Vibration Test: X axis Random Vibration Test: Y axis Random Vibration Test: Z axis Mechanical Shock Test: +X axis 5. 6.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_


t (886-2) 2299-3279 f (886-2) 2299-9558



TEST REPORT

Report No.:	HC:	50159A/	2016
Page:	7	of	7

Test Photos--Continued:



— — The End of Test Report — — –

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the alternated to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558