

## TEST REPORT

Report No.: HC80078/2020 Page: 1 of 14 September 9, 2020 Date:

VECOW CO., LTD. 3F., NO.10, JIANKANG RD., ZHONGHE DIST., NEW TAIPEI CITY 23586, TAIWAN

The following merchandise was submitted and identified by the vendor as: Product Description: SPC-5000 Series Style/ Item No.: SPC-5100/ No.1; SPC-5200/ No.1 Quantity: Total 2 sets **Testing Period**: Aug. 17, 2020 to Sep. 8, 2020

We have tested the submitted sample(s) as requested and the following results were obtained: Test Required: (According to client's test specification, please see following sheets in detail.)

- 1. High Temperature Test --I
- 2. High Temperature Test -- II
- 3. Low Temperature Test
- 4. Random Vibration Test
- 5. Mechanical Shock Test

Test Results :

-PLEASE SEE ATTACHED SHEETS-

Signed for and on behalf of SGS TAIWAN Ltd.

Allen Wang Asst. Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com.tw/Terms-and-Conditions</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/en/terms-and-conditions</u> and, for electronic format issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest externt / No 21. Write the company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest externt / No 21. Write the company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest externt / No 21. Write the under the limitation forme to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路31號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com

Member of SGS Group



TEST REPORT

Report No.:	HC80078/2020		020
Page:	2	of	14

e	Brand	Model	Serial No.
& Humidity Chamber	GIANT FORCE	GTH-225-40-CP-AR	MAA1807-009
tions:			
(25 ± 3) °C			
<u>(55 ± 20)% RH</u>			
No.31, Wu Chyuan	Road, New Taip	ei Industrial Park, Wu	ıKu District,
New Taipei City, Ta	aiwan.		
<u>n:</u>			
Operating (execute	"BurnIn")		
<u>85 °C</u>			
<u>95 % RH</u>			
16 hours			
	$\frac{\text{tions:}}{(25 \pm 3) \degree C}$ $(55 \pm 20) \% \text{ RH}$ $\frac{\text{No.31, Wu Chyuan}}{New Taipei City, Ta$	& Humidity Chamber GIANT FORCE <u>(25 ± 3) °C</u> (55 ± 20) % RH <u>No.31, Wu Chyuan Road, New Taipe</u> <u>New Taipei City, Taiwan.</u> <u>n:</u> <u>Operating (execute "BurnIn")</u> <u>85 °C</u> <u>95 % RH</u>	& Humidity Chamber GIANT FORCE GTH-225-40-CP-AR          tions:       (25 ± 3) °C         (55 ± 20) % RH         No.31, Wu Chyuan Road, New Taipei Industrial Park, Wu         New Taipei City, Taiwan.         n:         Operating (execute "BurnIn")         85 °C         95 % RH

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Connect the specimen with rated power, then execute test program "Burn in test" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC80078/2020		020
Page:	3	of	14

**Reliability Laboratory** 

Style/Item No.:

SPC-5100/ No.1

Total 1 set

Test Result:

Quantity:

Specimen:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
SPC-5100/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC80078/2020		020
Page:	4	of	14

#### **Reliability Laboratory**

## 2. High Temperature Test -- II:

Test Equipment:				
Nam	e	Brand	Model	Serial No.
Programmable Temperature	& Humidity Chamber	GIANT FORCE	GTH-225-40-CP-AR	MAA1807-009
Lab Environmental Condi	itions:			
Ambient temperature:	(25 ± 3) °C			
Ambient humidity:	$(55 \pm 20)$ % RH			
,				
Test Location:	No.31, Wu Chyuan	Road, New Taip	ei Industrial Park, Wu	ıKu District,
	New Taipei City, Ta	aiwan.		
Test Method/ Specificatio	<u>n:</u>			
Sample Condition:	Operating (execute	"BurnIn")		
Test Temperature:	<u>70 °C</u>			
Test humidity:	<u>95 % RH</u>			
Test Duration:	16 hours			

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Connect the specimen with rated power, then execute test program "Burn in test" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路31號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC80078/2020		020
Page:	5	of	14

**Reliability Laboratory** 

Specimen:

Style/Item No.: Quantity:

SPC-5200/ No.1 Total 1 set

## Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
SPC-5200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC80078/2020		020
Page:	6	of	14

**Reliability Laboratory** 

Name	e	Brand	Model	Serial No.
Programmable Temperature	& Humidity Chamber	GIANT FORCE	GTH-225-40-CP-AR	MAA1807-009
Lab Environmental Condi	tions:			
Ambient temperature:	<u>(25 ± 3) °C</u>			
Ambient humidity:	<u>(55 ± 20)% RH</u>			
Test Location:	No.31, Wu Chyuan	Road, New Taip	ei Industrial Park, Wu	Ku District,
	New Taipei City, Ta	aiwan.		
Test Method/ Specification	<u>n:</u>			
Sample Condition:	Operating (execute	"BurnIn")		
Test Temperature:	<u>-40 °C</u>			
Test Duration:	16 hours			

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Connect the specimen with rated power, then execute test program "Burn in test" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路31號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com Member of SGS Group



## TEST REPORT

Report No .:	HC80078/2020		20
Page:	7	of	14

Specimen: Style/Item No.:

Quantity:

SPC-5100/ No.1; SPC-5200/ No.1 Total 2 sets

#### Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
SPC-5100/ No.1	No visible damage	Normal
SPC-5200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



# TEST REPORT

Report No.:	HC80078/2020		
Page:	8	of	14

#### 4. Random Vibration Test:

#### Test Equipment:

Name	Brand	Model	Serial No.
Vibration Tester	UNHOLTZ-DICKIE	SAI60-H560BAC/2/ST	474
Controller	Dactron	LASER	7110357
Control Accelerometer	PCB	353B34	LW213529

## Lab Environmental Conditions:

Ambient temperature:	<u>(25 ± 3) °C</u>
Ambient humidity:	(55 ± 20) % RH

#### Test Location:

No.31, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan

#### Test Method/ Specification:

Test method:	IEC 60068-2-64	4, Edition 2.0: 200	<u>)8</u>	
Sample condition:	Operating (exec	ute "BurnIn Test"	<u>")</u>	
Wave form:	Random			
Frequency:	<u>(5 ~ 500) Hz</u>			
	Frequency (Hz)	Left Slope (dB/Oct.)	PSD (g <sup>2</sup> /Hz)	Right Slope (dB/Oct.)
	5	—	0.05	0
	500	0	0.05	
	⊂⇒ equivalent	t to 5.0 G <sub>rms</sub>		50
Direction:	X, Y, Z axes (se	e photo 8 ~ 11)		
Duration:	30 minutes/ axis	<u>s</u>		

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Connect the specimen with rated power, then execute test program "Burn in test" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/ 新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com Member of SGS Group



## TEST REPORT

Report No.:	HC80078/2020		
Page:	9	of	14

Specimen:

Style/Item No.: Quantity:

SPC-5100/ No.1; SPC-5200/ No.1 Total 2 sets

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
SPC-5100/ No.1	No visible damage	Normal
SPC-5200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.



Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



# TEST REPORT

Report No.:	HC80078/2020		
Page:	10	of	14

## 5. Mechanical Shock Test:

Test	Eq	ui	pment:	

Name	Brand	Model	Serial No.
Shock Test System	LANSMONT	95-115D	M17656
Data Acquisition & Analysis System	LANSMONT	TP4 8A-CH SML 1115-001	1115-001
ICP Accelerometer	PCB	353M288	196437

## Lab Environmental Conditions:

Ambient temperature:	( <u>25 ± 3) °C</u>
Ambient humidity:	(55 ± 20) % RH

Test Location:

No.33, Wu Chyuan Road, New Taipei Industrial Park, WuKu District, New Taipei City, Taiwan

## Test Method/ Specification:

Test method:	IEC 60068-2-27, Edition 4.0: 2008
Sample condition:	Operating (execute "BurnIn")
Pulse shape:	Half-sine
Acceleration:	<u>50 g</u>
Pulse duration:	<u>11 ms</u>
Shock direction:	<u>6 faces (<math>\pm X</math>, <math>\pm Y</math>, <math>\pm Z</math> axes, see photo 12 ~ 17)</u>
No. of shock:	3 shocks/ axis (total 18 shocks)

- Examine the appearance of specimen by visual check and perform functional check after this test.
- Functional check: Connect the specimen with rated power, then execute test program "Burn in test" while performing functional check.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



## TEST REPORT

Report No.:	HC80078/2020		
Page:	11	of	14

Specimen:

Style/Item No.: Quantity:

SPC-5100/ No.1; SPC-5200/ No.1 Total 2 sets

Test Result:

Check Item Style/ Item No.	Appearance check (Visual check)	Functional check
SPC-5100/ No.1	No visible damage	Normal
SPC-5200/ No.1	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.




Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC8	0078/20	)20
Page:	12	of	14

Test Photos:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



**TEST REPORT** 

Report No .:	HC8	0078/20	)20
Page:	13	of	14

Test Photos--Continued:

7. Low Temperature Test	8. Random Vibration Test: X axis
The bow reinperturbed rest	
9. Random Vibration Test: Y axis	10. Random Vibration Test: Z axis
11. Random Vibration Test: Z axis	12. Mechanical Shock Test: +X axis

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/ent/erms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forger or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fulles extend to the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/ 新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558



Report No.:	HC8	0078/20	)20
Page:	14	of	14

Test Photos--Continued:

ThotosContinued.	
13. Mechanical Shock Test: -X axis	14. Mechanical Shock Test: +Y axis
15. Mechanical Shock Test: -Y axis	16. Mechanical Shock Test: +Z axis
17. Mechanical Shock Test: -Z axis	18. Functional check

## – The End of Test Report — –

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份復製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sqs.com/ent/erms-and-conditions/terms-and-conditions of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsfitication of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Reliability Laboratory/ No.31, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan 可靠度實驗室/ 新北市五股區新北產業園區五權路 31 號 t (886-2) 2299-3279 f (886-2) 2299-9558